



# Customer Release Notes

## Fiery XF, version 8.0.5

Fiery® is pleased to announce the release of Fiery XF 8.0.5. This latest Fiery software release is a server update for Fiery proServer and Fiery XF 8.0, which updates the Fiery XF server from 8.0, 8.0.1, 8.0.2, 8.0.3, or 8.0.4 to 8.0.5.

### New printer drivers

- Agfa
  - Jeti Condor RTR5200 S (Printer Option Group 6)
  - Jeti Condor RTR5200 HS (Printer Option Group 6)
- Canon
  - Arizona 135 GT (Printer Option Group 7)
  - Arizona 1340 GTF, 1360 GTF, 1380 GTF (Printer Option Group 7)
  - Arizona 1340 XTF, 1360 XTF, 1380 XTF (Printer Option Group 7)
  - Arizona 2340 GTF, 2360 GTF, 2380 GTF (Printer Option Group 7)
  - Arizona 2340 XTF, 2360 XTF, 2380 XTF (Printer Option Group 7)
- ChengHe
  - i Press S Plus (Printer Option Group 4)
  - i Press X Plus (Printer Option Group 4)
- EFI
  - Pro 30h+
- EPSON
  - SureColor SC-T56X0D (Printer Option Group 4)
  - SureColor SC-T56X0DM (Printer Option Group 4)
  - SureColor SC-T76X0D (Printer Option Group 4)
- KEUNDO
  - SQ2216A (Printer Option Group 6)



- Ricoh
  - Pro TF6250 (Printer Option Group 7)
  - Pro TF6251 (Printer Option Group 7)
- Roland DG
  - TrueVIS XP-640 (Printer Option Group 6)
    - Support for CMYK
- X-Roland
  - JH 1290F (Printer Option Group 4)
  - JH 1301F (Printer Option Group 4)
  - JH 1302F (Printer Option Group 4)
  - JH 1304F (Printer Option Group 4)
- W+D
  - Tlprint (Printer Option Group 6)

## Updated printer drivers

- EFI
  - Pro 30f+
    - Added double clear ink support
  - VUTEk F-Q3r/F-Q5r [FAST DRIVE]
    - Added print modes:
      - 4C-CCWC-B-Coat\_F-Matte-Q
      - 4C-CCWC-B-Coat\_F-Matte-C1-Q
      - 4C-CCWC-B-Coat\_F-Matte-C2-Q
      - 4C-CWBWC-Coat\_F-Matte-C1-Q
      - 4C-CWBWC-Coat\_F-Matte-C2-Q
      - 4C-CWC-B-Coat\_F-Matte-Q
      - 4C-Backlit-Coat\_F-Matte-Q
  - VUTEk Q3r/Q5r [FAST DRIVE]
    - Added print modes:
      - 4C-CCWWCC-B-C1-X
      - 4C-CCWWCC-B-C2-X

- 7C-4Pass-Q
- 7C-4Pass-Q
- VUTEk X3r/X5r [FAST DRIVE]
  - Added CMYKcmk color mode
  - Added print modes:
    - 7C-4Pass-X
    - 7C-6Pass-X
    - 7C-8Pass-X
    - 7C-9Pass-X
    - 7C-10Pass-X
    - 7C-Backlit-X
    - 7C-White-Under-X
    - 7C-White-Over-X
    - 7C-CWC-X
    - 7C-CWC-C1-X
    - 7C-CWC-C2-X
    - 7C-CWC-B-X
    - 7C-CWC-B-C1-X
    - 7C-CWC-B-C2-X
    - 7C-Coat-Gloss-X
    - 7C-Coat-Matte-X
    - 7C-White-Under-Coat-Gloss-X
    - 7C-White-Under-Coat-Matte-X

## New measuring device support

- Barbieri Spectro Swing qb supported in Color Tools, Color Editor, and Server Manager (control strips and DynamicWedge support).

## New industry-standard support

- PANTONE® FASHION, HOME + INTERIORS (2024) Library update, adding 175 new colors.

## Connectivity enhancement

- Implementation of the response "Return Queue Entry" to align JDF support with Fiery cutsheet.

## New operating system support

Fiery XF server 8.0.5 newly supports the following operating systems:

- Windows Server 2025
- Windows 11 24H2

## Fixed issues

### Fiery XF 8.0.5 related fixes

- Fiery XF server-related fixes:
  - Renaming of "Channel" to "Criteria" on automatically printed verification label on printers with embedded measurement devices (for instance EPSON SureColor SC-P7500).
  - Fixed a problem with license recognition for Printer Option Super Wide Format.
  - Fixed a problem with virtual printers on macOS 15.1.
- Printer driver-related fixes:
  - Fixed a problem where the label after verification shows Delta H instead of Delta Ch.
  - Fixed a problem on Agfa Jeti Mira MG2732 where the creation of media size larger than 96 inches was impossible.
  - Fixed a problem on HP Stitch S500 where an error occurs when trying to create a calibration in Color Tools.
  - Fixed the missing log of job media and ink consumption on HP Stitch S500.
  - Fixed problems with HP DesignJet Z9 RGB and the embedded measurement device.
  - Fixed an issue on EFI VUTEk Q5r with 7 color mode, where the linearization TIFF separation files of Y and LY are distorted.
  - Fixed an issue on Epson SC P-7500/9500 where linearization failed with media type Canvas Satin.
  - Fixed an issue with Canon imagePROGRAF PRO6600 with missing media types and failing Profile synchronization.
  - Fixed an issue with EFI VUTEk Q5r [FAST DRIVE] with distorted linearization TIFF separation files of yellow and light yellow.
  - Fixed an issue with HP Latex 3600, which was not working after upgrading to Fiery XF 8.0.4.
- FAST RIP-related fixes:
  - Fixed an issue with lines or unwanted artifacts in the output.
- Cutting-related fixes:
  - Fixed a problem when using an older ZCC version.

## Availability

- The Fiery XF server 8.0.5 update is available as an online update through Fiery Server Control for all configurations of Fiery proServer and Fiery XF version 8.0.
- Alternatively, the Fiery XF server 8.0.5 update can be downloaded from the [Fiery Download Center](#).

## Additional notes

- Fiery proServer and Fiery XF solutions are made from multiple software applications. A server application (Fiery XF server), a client application (Fiery Command WorkStation), plus color applications (Color Profiler Option and Color Verifier Option included within Fiery Color Profiler Suite).
- The following overview informs you about the Fiery XF server, Fiery Command WorkStation, and Fiery Color Profiler Suite versions required for the full support of features with Fiery XF 8.0.5:

|                                    | Fiery XF server   | Fiery Command WorkStation Package   | Fiery Color Profiler Suite   |
|------------------------------------|---|---|--|
| <b>Fiery XF 8.0.5</b>              | 8.0.5   | 7.1.0.423 or later  | 5.8.0.25 or later  |
| <b>Supported Operating Systems</b> | Microsoft Windows 10 (64-bit)<br>Microsoft Windows 11<br>Microsoft Windows 11 24H2<br>Microsoft Windows Server 2016 (64-bit)<br>Microsoft Windows Server 2019<br>Microsoft Windows Server 2022<br>Microsoft Windows Server 2025 | Microsoft Windows 10 (64-bit)<br>Microsoft Windows 11<br>Microsoft Windows 11 24H2<br>Microsoft Windows Server 2016 (64-bit)<br>Microsoft Windows Server 2019<br>Microsoft Windows Server 2022<br>Microsoft Windows Server 2025<br>macOS 12<br>macOS 13<br>macOS 14<br>macOS 15 | Microsoft Windows 10 (64-bit)<br>Microsoft Windows 11<br>Microsoft Windows 11 24H2<br>Microsoft Windows Server 2022<br>Microsoft Windows Server 2025<br>macOS 12<br>macOS 13<br>macOS 14<br>macOS 15 |

- The latest Fiery Command WorkStation and Fiery Color Profiler Suite versions are available through the Fiery Software Manager or the [Fiery Download Center](#) in the **Application Software and Tools** section.

## Software Maintenance & Support Agreement (SMSA)

Fiery Software Maintenance & Support Agreements (SMSA) for Fiery proServer and Fiery XF provide an ongoing stream of features, improvements, fixes, and the latest printer and cutter drivers. Fiery XF 8.0.5 is available at no additional charge for all customers with their Fiery software covered under this agreement.

For more information, please contact your local Fiery XF dealer or visit <https://fiery.com/XF>.

Fiery's portfolio of integrated solutions increases productivity and improves your bottom line. Find out more at [www.fierey.com](http://www.fierey.com).